

TABELA DE CONVERSÃO DE POLEGADAS EM MILÍMETROS

Pol.	mm	Pol.	mm	Pol.	mm	Pol.	mm
1/32	0,794	29/32	23,02	1 25/32	45,24	3 5/8	92,08
1/16	1,588	15/16	23,81	1 13/16	46,04	3 3/4	95,25
3/32	2,38	31/32	24,61	1 27/32	46,83	3 7/8	98,43
1/8	3,18	1	25,40	1 7/8	47,62	4	101,60
5/32	3,97	1 1/32	26,19	1 29/32	48,42	4 1/4	107,95
3/16	4,76	1 1/16	26,99	1 15/16	49,21	4 1/2	114,30
7/32	5,56	1 3/32	27,78	1 31/32	50,00	4 3/4	120,65
1/4	6,53	1 1/8	28,57	2	50,80	5	127,00
9/32	7,14	1 5/32	29,37	2 1/16	52,39	5 1/2	139,70
5/16	7,94	1 3/16	30,16	2 1/8	53,96	6	152,40
11/32	8,73	1 7/32	30,95	2 3/16	55,56	6 1/2	165,10
3/8	9,53	1 1/4	31,75	2 1/4	57,15	7	177,80
13/32	10,32	1 9/32	32,54	2 5/16	58,74	8	203,20
7/16	11,11	1 5/16	33,34	2 3/8	60,32	9	228,60
15/32	11,91	1 11/32	34,13	2 7/16	61,91	10	254,00
1/2	12,70	1 3/8	34,92	2 1/2	63,50	11	279,40
17/32	13,49	1 13/32	35,72	2 9/16	65,09	12	304,80
9/16	14,29	1 7/16	36,51	2 5/8	66,67	13	330,20
19/32	15,08	1 15/32	37,30	2 11/16	68,26	14	355,60
5/8	15,87	1 1/2	38,10	2 3/4	69,85	15	381,00
21/32	16,67	1 17/32	38,89	2 13/16	71,44	16	406,40
11/16	17,46	1 9/16	39,69	2 7/8	73,02	17	431,80
13/16	18,26	1 19/32	40,48	2 15/16	74,61	18	457,20
3/4	19,05	1 5/8	41,27	3	76,20	19	482,60
25/26	19,84	1 21/32	42,07	3 1/8	77,79	20	508,00
13/16	20,64	1 11/16	42,86	3 1/4	82,55	21	533,40
27/32	21,43	1 23/32	43,65	3 3/8	85,73	22	558,80
7/8	22,22	1 3/4	44,45	3 1/2	88,90	23	584,20